

# Schedule 11 - Suggested Checklist for Preliminary Assessment of Site Conditions in relation to the preparation of Site Stability Reports

6 LEWIS STREET BALGOWLAH HTS.

1. Site Location (Street and Position in street - above or below; Site dimensions - block shape & size):
2. Geotechnical Area in which the site is located: **G4**
3. Proposed development (general description, including maximum excavation depths, maximum fill depths, and proximity to existing structures): **NEW ABOVE GROUND POOL + CARPORT <1m EXC +**
4. Existing site: description eg. topography, slope angles (in degrees), exposures of rock and soil, existing site development, evidence of possible slope instability: **NO**
5. Recommendations: based on the above items, and the flowchart below that indicates the principal factor(s) considered in the assessment, it is recommended that:
  - geotechnical assessment is required; or
  - geotechnical assessment is not required. **✓ REPORT NOT REQUIRED**
  - other comments:

DATE OF ASSESSMENT : **14/3/20**

ASSESSMENT BY : **BRIANNA SWAN**

## CHECKLIST FOR COUNCIL'S ASSESSMENT OF SITE CONDITIONS AND NEED FOR GEOTECHNICAL REPORT

