

6 Wearden road, Belrose.

Statement of works undertaken

- **Internal walls built to create bedroom 1 & 3**
- **Internal walls build to create fridge location and entrance wall to divide dining room**
- **Replaced timber rotten Windows and doors with Aluminum windows & doors**
- **Added 1 x window to eastern elevation & 1 x window to northern elevation & 1 window made into a Door way on South Elevation**
- **Timber Retaining wall with Timber fence to rear boundary**
- **Boundary firewall to BCA standard (60/60/60) (eastern side)**