Schedule 11 - Suggested Checklist for Preliminary Assessment of Site Conditions in relation to the preparation of Site Stability Reports

- Site Location (Street and Position in street above or below; Site dimensions block shape & size). Lewis St, Balgowlah
- Geotechnical Area in which the site is located): 64
- Proposed development (general description, including maximum excavation depths, maximum fill depths, and proximity to existing structures): Awning
- 4. Existing site: description eg. topography, slope angles (in degrees), exposures of rock and soil, existing site development, evidence of possible slope instability: No
- Recommendations: based on the above items, and the flowchart below that indicates the principal factor(s) considered in the assessment, it is recommended that:
 - geotechnical assessment is required; or
 - geotechnical assessment is not required. Geotech assessment not required
 - other comments:

DATE OF ASSESSMENT: .30/4/24....

ASSESSMENT BY : P. Holmes

CHECKLIST FOR COUNCIL'S ASSESSMENT OF SITE CONDITIONS AND NEED FOR GEOTECHNICAL REPORT



