

2 8 NOV 2016

General Manager Pittwater Council PO Box 882 Mona Vale NSW 1660

Dear Sir/ Madam

Development Consent No. N0390/14 Construction Certificate No. 2015/5438

For Council's information, please find enclosed the following:

- 1. Occupation Certificate No. 2015/5438.
- 2. A cheque for \$36.00 being Council's administration fee to accept the above. Please send receipt to Insight Building Certifiers, PO Box 326, Mona Vale 1660.

Yours faithfully,

Tom Bowden

Insight Building Certifiers Pty Ltd

2 8 NOV 2016
CUSTOMER SERVICE

2-401607



Determination of a Final Occupation Certificate Application

Made under Sections 109C(1)(c) and 109H of the Environmental Planning and Assessment Act 1979

Final Occupation Certificate No: 2015/5438

Land to which this certificate applies:

Address: 12 Bertana Crescent, Warriewood

Lot No: 16 DP No: 233448

I approve the issuing of this Final Occupation Certificate and certify that:

- I have been appointed as the Principal Certifying Authority under Section 109E of the Environmental Planning & Assessment Act 1979.
- Current Development Consent No. N0390/14 is in force for this development.
- Construction Certificate No. 2015/5348 has been issued with respect to the plans and specifications for Alterations & Additions to Existing Dwelling.
- The building is completed in accordance with its classification under the Building Code of Australia.
- Refer to the attached Schedule of all critical stage inspections and Compliance Certificates relied upon to issue this Occupation Certificate.

Determination date: 28 November 2016

Tom Bowden

Accredited Certifier - Accreditation No. BPB0042

Schedule of critical stage inspections carried out or missed by the Principal Certifying Authority (Clause 151, 162A, 162B & 162C of the Environmental Planning & Assessment Regulations 1994)

The state of the s		
Critical Stage Inspections	Inspected or Missed	Date Inspected
Prior to issue of a Construction Certificate	Inspected	12/03/2015
Excavation for footings	n/a	n/a
Prior to pouring of any insitu reinforced concrete	n/a	n/a
Prior to the covering of any framework	Inspected	03/07/2015
Prior to covering waterproofing in any wet area	n/a	n/a
Prior to covering any stormwater drainage connections	n/a	n/a
Other required inspections	n/a	n/a
Final Inspection	Inspected	09/12/2015 & 16/12/2015

Schedule of Compliance Certificates or other documentary evidence relied upon to issue the Final Occupation Certificate

Nil



BUILDING INSPECTION REPORT

	/ /
Date of Insp	pection 3/2//5'
hercent Warm	iewood
CC No 2015 / 5-438	CDC No
Ph No	DUIU 972 337
Footings and Excavation	Waterproofing
Steel Placement	Stormwater
Floor Framing / Slab	Pool Fence
Wall Framing	Final Inspection
Roof Framing	Photographic record
evelopment Certificate.	infications as approved in that
er and contact the Principal Cer e of \$ will be charg IED OUT.	
Den	
s de s	
creditation No. BABODIS	1-1
	CC No 2015 / S-428 Ph No Ph No Footings and Excavation Steel Placement Wall Framing Roof Framing Roof Framing Identificate and species of \$