



#### FINAL OCCUPATION CERTIFICATE

Date Application Received	09-09-2013		PITTWATER	CONNCIL
Council	Pittwater	DA Number	N0161/13	
Occupation Certificate No.	2014-254		Date Approved	21-10-14
CC No.	2013-221		Date Approved	17-09-13
Certifying Authority	Craig Formosa		·	·
Accredited Certifier	Craig Formosa		Accreditation No.	BPB0124
Accreditation Body	Building Profession	onals Board		<del></del>
APPLICANTIDETALES				
Name	Heidi Middleton &	Nicholas Plowman	Contact Number	0418 888 468
Address	136 Pacific Road,	Palm Beach NSW 2108	· · · · · · · · · · · · · · · · · · ·	<u> </u>
OWNERDETALES				
Name	Heidi Middleton &	Heidi Middleton & Nicholas Plowman		
Address	136 Pacific Road,	Palm Beach NSW 2108		
DEVECORMENTIDETAIL				
Subject Land	136 Pacific Road,	Palm Beach NSW 2108	Lot No. 12B	DP 13374
Description of Development	Alterations and additions to an existing dwelling			
Class of Building	1a Value of Work S		\$300,000.00	
	THE BUILDING	IS SUITABLE FOR OCCU	PATION	
Certificates Attached	Form 3 Geotech, 7	tion Reports, Builders Glaz Fermite, Smoke Detector, V	ing to BAL 12.5, Structu Vaterproofing.	ıral Engineers,
REGORD OF INSPECT	NE .			
Site Inspection prior to issue of Construction Certificate 12-09-			12-09-13	
Clab Chaire			04-03-14	
Timber Frame – prior to lining 04-03-			04-03-14	
Waterproofing – wet area				16-10-13
*** Wet aleas			11-03-14	
Final Inspection - issue of	f Occupation Certifica	te		20-05-14

I, Craig Formosa, as the certifying authority am satisfied that;

- (a) the building will not constitute a hazard to the health or safety of the occupants,
- (b) a current Development Application is in force for the building,
- (c) a current Construction Certificate has been issued for the building in respect to the plans and specifications for the building,
- (d) the building is suitable for its use under the Building Code of Australia, and
- (e) all the pre-cribed conditions of development consent have been satisfied.

Signed:

Date: 21-10-2014

PCA Accreditation No. BPB0124

Accreditation Body: Building Professionals Board

906 REC: 360996 7/11/14



COwner	☐ Applicant	D Builder	Other
Name //	eidi Middlett	on & Marma	// Tel/Email
<b>PROPERTY</b>	ADDRESS		
/36	Pacific	Mood Ya	Im Beach
INSPECTIO	ON TYPE		en production of the second of
	ME CC	Ima	
	ON OUTCOME		Action Required (read with NOTES below)
Certifier Opin	<u> </u>		M. S. Sanda, C. S. Sepper, M. S. Sanda, S. Sanda, C. Sanda, S. Sanda, Sanda, S. Sanda, S. Sanda, S. Sanda, S. Sanda, S. Sanda, S. San
ļ <u>~:</u>	stage is Satisfactory		☐ NO re-inspection required
	stage is Satisfactory sub		<del></del>
	stage is Not Satisfactory	/	☐ Tick if result has also been given verbally
NOTES			
1/re	CC isson	e inspotion:	Sotisfacti
		<del>-/</del>	
<b> </b>			
<b></b>			
<b> </b>			
/			
	A		
Λ			
T 7	Vormer		12 1 9 12013.
Angradited Co	ertitier - BPB <u>0/29</u>	2	/
- CONDUMENTO			

FORM Building Certifiers Pty Ltd ABN 76 134 030 710 | PO Box 1824, Dee Why NSW 2099 | T/F +61 2 8921 9313 | info@formbc.com | www.formbc.com



☐ Owner	☐ Applicant	Builder	☐ Other
Name			Tel/Email
PROPERTY			1900 F. 18 18 18 18 18 18 18 18 18 18 18 18 18
	CIFIC RD, P	ALM BEAC	$\mathcal{H}$
INSPECTIO	00.00		
		AIN BEDKOC	DM I BATHROOM
	NOUTCOME	and a second	
Certifier Opini			Action Required (read with NOTES beli
Inspection st	tage is Satisfactory		☐ NO re-inspection required
☐ Inspection st	tage is Satisfactory sub	ject to Action Require	d ☐ Re-inspection required
☐ Inspection st	tage is Not Satisfactory		☐ Tick if result has also been given verba
NOTES			
WATER F	RODANG SY	ATTSFACTORY	Y TO PLOOR ONLY
ABOR OTO	DPS PROVIDE	D TO PRE	HMETER OF BEDROOM
PROVIDE	CERTIFICATE	CT - 110	DOSED PATERIBODER
		11.011 00	and white or
		<del></del>	
	77		
	····		
	-		
<del> </del>			
	· · · · · · · · · · · · · · · · · · ·		
$\overline{}$			
$$ $\rho V$	<del></del>		
_ Ufor	moz-	HGTALL	<u>16 1 10 120 13</u>
Accredited Certi	fier - BPB 0124		Date




	tion of the state	4.0	
☐ Owner	☐ Applicant	G Builder	☐ Other
Name COVIE	APORACI BUL	SERS-MARK	Tel/Email
PROPERTY	ADDRESS		
136 PA	CIFIC RU, 1	PARM BEACI	4
INSPECTION	The second secon		
the Contract of the second contract of the second of the s	ERS, FRAMES	NG	
INSPECTION	and the second of the second o		
Certifier Opinio	on .		Action Required (read with NOTES below
☐ Inspection sta	age is Satisfactory		2 NO re-inspection required
Inspection sta	age is Satisfactory subj	ect to Action Required	☐ Re-inspection required
☐ Inspection sta	age is Not Satisfactory		☐ Tick if result has also been given verbal
NOTES			
-STEEL 1	RENFORCEM	ENT IN DE	ACE FOR STAIRS
-TRAMING	F AZL DO	VE SATISFI	ACIORY
ENGINEES	HAS INSA	(CTG) x 70	ACE FOR STAIRS ACTORY PROVIDE REPORT
<u> </u>			
<del></del>			
		· · · · · · · · · · · · · · · · · · ·	
· · · · · · · · · · · · · · · · · · ·			
		<del></del>	
			4 13 120 14
Accredited Certific	er - BPB	714.	Date



Downer Japplicant Builder Jother  Name Mark Plantempormy building TeVEmail  PROPERINADDRESS  136 Partic Load Plan Grant  INSTECTIONING  Water pooking  Inspection stage is Satisfactory  Inspection stage is Satisfactory  Inspection stage is Not Satisfactory  Inspection stage is Not Satisfactory  That if result has also been given verbally  ROTES  Wife Showe substactory wate stop angle poorblad  Provide a celificate from waterpoole.  According Certifier - BPB 124  Date				
136 Reife load Relm Geach.  INSTITUTION TIME  Wite profing.  INSTITUTION OUR COME  Certifier Opinion  Action Required (read with NOTES below)  Inspection stage is Satisfactory  Inspection stage is Satisfactory who re-inspection required  Inspection stage is Not Satisfactory  Inspection stage is Not Satisfactory  Include the satisfactory with the salso been given verbally  NOTES  What to showe satisfactory with salso been given verbally  NOTES  Now de a ceft freate from waterpoole.  According Certifier - BPB 0124  Date				J Other
136 Reife load Relm Geach.  INSTITUTION TIME  Wite profing.  INSTITUTION OUR COME  Certifier Opinion  Action Required (read with NOTES below)  Inspection stage is Satisfactory  Inspection stage is Satisfactory who re-inspection required  Inspection stage is Not Satisfactory  Inspection stage is Not Satisfactory  Include the satisfactory with the salso been given verbally  NOTES  What to showe satisfactory with salso been given verbally  NOTES  Now de a ceft freate from waterpoole.  According Certifier - BPB 0124  Date	Name Mark	D Contemporary	building	Tel/Email
INSPECION TO THE  WITE Proofing.  INSPECION OUTCOME  Certifier Opinton  Inspection stage is Satisfactory  Inspection stage is Satisfactory subject to Action Required  Inspection stage is Not Satisfactory  Inspection stage is Not Satisfactory  Inspection stage is Not Satisfactory  Inck if result has also been given verbally  NOTES  WITE Stop angle portolical  Insufe a ceft ficule from waterpoote.  Insufe a ceft ficule from waterpoote.			the state of the s	
INSPECTION OF THE CONTROLL STATE OF THE CONTROL STATE OF	136 Pacit	ic load Palm	n Beach	
Action Required (read with NOTES below)				
Cortifier Opinion  Action Required (read with NOTES below)  Inspection stage is Satisfactory Inspection stage is Satisfactory subject to Action Required Inspection stage is Not Satisfactory Inspection required Inspection				
Inspection stage is Satisfactory  Inspection stage is Satisfactory subject to Action Required  Inspection stage is Not Satisfactory  Itolies  Why to showe substactory unter stop angle possible.  Provide a celificate from waterpoole.	The Marketine Marketine			
Inspection stage is Satisfactory subject to Action Required Inspection stage is Not Satisfactory Inspection required Insp				Action Required (read with NOTES below)
Inspection stage is Not Satisfactory  NOTES  Who showe substactory write stop angle provided.  Provide a cepitrate from waterproofe.	***************************************		4.1	<del></del>
NOTE:  - Who showe substactory, write stop angle possible.  - Provide a celificate from waterposte.  - It is a substactory with the stop angle possible.  - It is a substactory with stop angle possible.  - It is a substactory with stop angle possible.  - It is a substactory with stop angle possible.  - It is a substactory with stop angle possible.  - It is a substactory with stop angle possible.  - It is a substactory with stop angle possible.	☐ Inspection sta	ge is Satisfactory subject	to Action Required	☐ Re-inspection required
- We to showe satisfactory, unterstop angle provided.  - Provide a cetificate from waterpoole.	the state of the s	ge is Not Satisfactory		☐ Tick if result has also been given verbally
Accredited/Certifier - BPB 0/2 4- Date	The state of the s			
1	- Prov. Je	a cetificate	from water	e proste.
1				
1				
1				
1			· · · · · · · · · · · · · · · · · · ·	
1				
1				
1				
Accredited Certifier - BPB 012 4 Date				
Accredited Certifier - BPB 012 4 Date				
Accredited Certifier - BPB 012 4 Date				
Accredited Certifier - BPB 012 4 Date				
Accredited/Certifier - BPB 0/2 4 Date				11 1 3 120 14
	-			



☐ Owner	☐ Applicant	<b>№</b> Builder	☐ Other	
Name Norh	Thompson Co.	Japaray Bille	5- Tel/Email	· · · · · · · · · · · · · · · · · · ·
HROPERNY/	ADDRESS ***			
136 Parifi	c Road, Pa	Am Beach		
INSPECTION	IMRE			
Final.				
(IVELSE A 10)				
Certifier Opinion	**************************************		Action Required (read with	NOTES below)
☐ Inspection sta	ge is Satisfactory		NO re-inspection required	
Inspection sta	ge is Satisfactory sub	ject to Action Required	☐ Re-inspection required	
☐ Inspection sta	ge is Not Satisfactory		Tick if result has also been	given verbally
NOTES				
Sulder to 1.	ssie cetificai	ted for glazing	, were posting, white	ant posteche
JECANICA T	engineers rep.	<i>&gt;</i> ~ <i>f</i> ·		iq v
Had wired	smuhe detect	es installed to	s all levels.	
		existing terrace		
			Lived non-openable	windows
- Works con	pleted satisfac	by and in ac	consume to BAL 12.	5
		stilled to stan		
5m 3 1	be issued by	4 Geotechnical	Engineer	
Builde to	issne Pea let	ter of couple	ence for Basic regues	conce k
All counci	1 intrastrict	re allows t	beer from any demi	1.01
result of	works.	11	buy same	aft as a
104000 Of				
·			,,	
//	/			
-Ch	mox		20 15 120 14	
Accredited Certifie	er - BPB 0/24	-	Date	



#### **GLAZING CERTIFICATION**

#### **PROJECT DETAILS**

Date: 17th September 2014

Site Address: 136 Pacific Rd Palm Beach

**Builders Name:** Contemporary Builders PTY LTD

Development Consent No. DA No: N0161/13

Construction Certificate No. CC0272/13

I hereby certify that the glazing for windows, doors and glazing panels, has been designed and installed in accordance with Part 3.6 of Volume 2 of the Building Code of Australia, AS 2047-1999 "Windows in buildings — Selection and Installation" and/or AS 1288-2006 "Glass in buildings — Selection and Installation".

Visibility markings as required on glazing by Part 3.6.4.6 of the Building Code of Australia have been provided.

Glazing complies with BAL 12.5 requirements

Further, I am appropriately qualified and experienced to provide the certification for this component of the project.

Mark Thompson



r ezepe es

#### CERTIFICATE OF STRUCTURAL ADEQUACY

# Alterations 136 Pacific Rd, Palm Beach Structural

I hereby certify that I am a practising structural engineer, that I am a corporate member of the Institution of Engineers Australia in the fields of civil and structural engineering and that I am listed on the National Professional Engineers Register Section 3 (NPER-3) under the categories of Civil and Structural Engineering.

The site has been inspected under my supervision on September 16, 2013, February 28, 2014 and other supporting documentation provided, and I am satisfied that the works listed below are structurally adequate, as defined in the relevant Australian Standards listed, and have been carried out with the intent of the drawings noted.

This certificate is limited to the specific items mentioned above and makes no statement concerning the general adequacy of other elements on the site.

Works:

Structural steel lintel supporting new masonry up stairs to upper bedroom, topping slab to upper bedroom, steel support struts to existing steel beams supporting cantilevered slab in upper bedroom, new steel roof beams in upper bedroom, new steel lintel for double doors in upper bedroom, new reinforced concrete stairs from kitchen to dressing room (old garage), new roof framing in upper bedroom.

Standards:

AS 1170 (Structural actions)

AS1684 (Residential timber framed construction)

AS2870 (Residential slabs and footings)

AS3600 (Concrete structures) AS 4100 (Steel structures)

Drawings and instructions:

uctions: GNG Design drawings 12.051-1\_A, 2\_A, 3\_A, 4\_A, 5\_A 6\_A, 7\_A, 8\_A, 9\_A, dated 30.08.2013; email of strut detail dated September 16 2013; email dated September 25, 2013 - GNGDesign to Client regarding upper bedroom roof

beam sizes.

Glenn Grice

BE(Hons), MSc, MIEAust, C.P.Eng (Reg - NPER3)

July 16, 2014 Ref: 12.051-C01

# GEOTECHNICAL RISK MANAGEMENT POLICY FOR PITTWATER FORM NO. 3 – Post Construction Geotechnical Certificate to be submitted with Occupation Certificate or Subdivision Certificate

	Development Application		
		Name of Applicant	
	Address of site 136	PACIFIC ROAD PALM BEACH	
Declaration	on made by geotechnical	engineer on completion of the Development	
1, [	PETER THOMPSON	on behalf of Jack Hodgson Consultants Pty Ltd (Trading or Company Name)	
	(Insert Name)	(Trading or Company Name)	
on this the	4/09/2014		
Policy for F a current p referred to	Pittwater - 2009. I am authori rofessional indemnity policy below.	er, Engineering Geologist and/or Coastal Engineer as defined by the Geotechnical Risk Mar sed by the above organisation/company to issue this document and to certify the organisation of at least \$2million.; I prepared and/or verified the Geotechnical Report as per Form 1 date	n/company
Geotecnn	ical Report Details:	YSIS AND MANAGEMENT FOR PROPOSED ADDITIONS AND ALTERATIONS AT 136	
	PACIFIC ROAD PALM BE	FACH	
	Report Date: 15/05/13		I
	Author : BEN WHITE		1
	Author's Company/Orga	INISATION: JACK HODGSON CONSULTANTS PTY LTD	
and amen Report and	ded structural documents) d the Construction Certifica	m satisfied that the foundation materials, upon which the structural elements (as detaile of the development have been erected, comply with the requirements specified in the ate approved Structural Plans. during construction and to the best of my knowledge, I am satisfied that the developme	Geotechnical
D.A. No_	N0161/13	Date consent given17/07/2013.	
Consent ar plan that m	nd the Construction Certifica	cordance with the intent of the Geotechnical Report, and the requirements of the conditions te approved Structural Plans relating to the geotechnical issues (including any treatment and sk where reasonable and practical).	of Development l/or maintenance
will rely on reasonable	this certificate in regard to the	Council require this certificate prior to issuing an occupancy certificate for the development id the development having achieved the "Acceptable Risk Management" criterion defined in the we been taken to remove foreseeable risk.	entified above an Policy and that
List of all	work as executed drawing	s and Ongoing Maintenance plans relevant to geotechnical risk management.	
		Signature P.t. OLo. L.	
		Name PETER THOMPSON	
	,	Chartered Professional Status MIE Aust CPEng	
		Membership No. 146800	
		a Look Hedgeon Consultante Phyl td	

# COMPLIANCE CERTIFICATE

Address:	No. 136 Pacific Road, Palm Beach
Lot Number	
Builder:	Contemporary Builders
Home Owner:	
Date of Final Inspection:	23rd/9/14
Termite Management System	ı used:.
	Visual inspection zone
Our company has inspected t and we confirmed the follow	he Termite Management System used at above address ing:
<ul><li>➢ First floor addition</li><li>➢ AS3660.1 − 2000 (v</li></ul>	isual inspection zone)
Yours faithfully	
Name;	Fergus Bermingham
Company;	Design Pest Solutions P/L
Date;	28 <sup>th</sup> /09/14
State Licence No:	15-100387-001
Insurance Termite Ac	creditation No: 8850

# TKG ELECTRICAL CONTRACTOR

T&L Garner Pty Ltd ABN: 65 156 191 990 Lic #: 194750C Po Box 1015

Mona Vale 1660

26/09/2014

To Whom It May Concern:

RE: 136 Pacific Rd, Palm Beach.

I, Trent Garner hereby certify that all electrical work carried out by TKG Electrical Contractor, on the above mentioned address has been installed in accordance with AS/NZS 3000:2007 wiring rules and local supply authority.


All smoke detectors in the above mentioned address have been installed to Australian Standards AS3786-1993 Smoke Alarms and BCA 3.7.2

Inspected by

Trent Garner

**TKG Electrical Contractor** 

Contractor Licence No: 194750C



### Installation Certification for waterproofing of Wet Areas

#### **PROJECT DETAILS**

Date: 15th September 2014

Site Address: 136 Pacific Rd Palm Beach

**Builders Name:** Contemporary Builders PTY LTD

Development Consent No. DA: N0161/13

**Construction Certificate No. CC0272/13** 

#### **INSTALLATION DETAILS**

Installers Name: Mark Thompson

**Builders Lic No. 229453C** 

**Contact Number: 0412 585 892** 

Material Used: Aldridge, HPM - Megaflex

Scope of Works: Main bedroom and bathroom

I certify that the wet areas listed above have been installed to comply with the requirements of the Building Code of Australia and AS 3740 Waterproofing of wet areas at the above address.

Mark Thompson