

#### RECEIVED MONA VALE

-9 OCT 2014





#### **FINAL OCCUPATION CERTIFICATE**

Date Application Received	04/07/13					
Council	Pittwater DA Number N0165/12					
Occupation Certificate No.	2014-219	2014-219 Date App			18/0	09/14
CC No.	2013-149	2013-149 Date Approved			09/	09/13
Certifying Authority	Craig Formosa		·			
Accredited Certifier	Craig Formosa	Craig Formosa Accre			BPI	30124
Accreditation Body	Building Professionals	Board				
APPLICANT DETAILS	A STATE OF THE STA	Not the state of t				1
Name	Arclab Architectural				041	6 886 537
Address	P O Box 1239 Newpor	P O Box 1239 Newport Beach				
OWNER DETAILS		Constitution of the second				
Name	Jill Doyle	Jill Doyle				
Address	16A Rednal Street, Mo	16A Rednal Street, Mona Vale NSW 2103				
DEVELOPMENT DETAIL	.s					
Subject Land	16A Rednal Street, Mo	16A Rednal Street, Mona Vale NSW 2103			DP	609008
Description of Development	Alterations & Additions	Alterations & Additions to an existing dwelling				
Class of Building	1a	1a			\$48,400.00	
	THE BUILDING IS S	UITABLE FOR OCC	UPATION			
Certificates Attached	Mandatory Inspection	Reports, Structural E	ngineers, S	Smoke Alarm.		
RECORD OF INSPECTI	ONS					
Site Inspection prior to issue of Construction Certificate				02/09/13		
Timber Frame – prior to lining				24/09/14		
Final Inspection – issue of Occupation Certificate				2	8/07/14	

#### CERTIFICATION

- I, Craig Formosa, as the certifying authority am satisfied that;
  - (a) the building will not constitute a hazard to the health or safety of the occupants,
  - (b) a current Development Application is in force for the building,
  - (c) a current Complying Development Certificate OR Construction Certificate has been issued for the building in respect to the plans and specifications for the building,
  - (d) the building is suitable for its use under the Building Code of Australia, and
  - (e) all the prescribed conditions of development consent have been satisfied.

Signed:

PCA Accreditation No. BPB0124

Accreditation Body: Building Professionals Board

Date: 18/09/14



## INSPECTION REPORT

□ Applicant □ Builder	Other			
Name Doylf	Tel/Email			
PROPERTY ADDRESS				
16A REDNAL ST. 1	MONA VALL			
INSPECTION TYPE				
PAE CC. Iswe				
INSPECTION OUTCOME				
Certifier Opinion	Action Required (read with NOTES below)			
Inspection stage is Satisfactory	□ NO re-inspection required			
☐ Inspection stage is Satisfactory subject to Action Required	☐ Re-inspection required			
☐ Inspection stage is Not Satisfactory	☐ Tick if result has also been given verbally			
NOTES				
	egasal & site			
Pre-CC issue- for Satisfactor				
soursfully				
	12 Maria Cara Cara Cara Cara Cara Cara Cara			
Accredited Certifier - BPB 0/24 Date				

FORM Building Certifiers Pty Ltd ABN 76134030710 | PO Box 1824, Dee Why NSW 2099 | T/F +61 2 8021 9313 | info@formbc.com | www.formbc.com



# **INSPECTION REPORT** 3965

Owner	Applicant	Builder	☐ Other		
Name Paul	Baggot		Tel/Email		
PROPERTY AD					
16A Red	nal st, M	ong Vale	•		
INSPECTION T					
Frame In					
INSPECTION C	UTCOME				
Certifier Opinion			Action Required (read with NO	OTES below)	
Inspection stage	e is Satisfactory		☐ NO re-inspection required		
☐ Inspection stage	e is Satisfactory subjec	et to Action Required	☐ Re-inspection required		
☐ Inspection stage	e is Not Satisfactory		☐ Tick if result has also been g	iven verbally	
NOTES					
- Approx 30	00 x 300	Galvanned	steel beam install	led	
over the	Kitchen	arcy sup	skel beam install	buck	
wall +		11			
- Timber	beams us	talled us	walls to lon	ndl	
				1	
lugmeer	to unsy	ued o	certify also.		
			J		
$\cap$					
lher	mon		241 09120 13		
Accredited Certifier - BPB 0174 Date					



### **INSPECTION REPORT** 5354

Owner	☐ Applicant	☐ Builder	☐ Other
Name JILL	DOYLE		Tel/Email
PROPERTY A			
16A Redr	al St. Monau	ale	
INSPECTION	TYPE		
final			
INSPECTION	OUTCOME		
Certifier Opinion	1		Action Required (read with NOTES below)
Inspection stage	ge is Satisfactory		☐ NO re-inspection required
☐ Inspection stag	ge is Satisfactory subject	to Action Required	☐ Re-inspection required
☐ Inspection stag	ge is Not Satisfactory		☐ Tick if result has also been given verbally
NOTES			
All works	sahisfoctory.	Provide the	following certificates
prior to H	ne issue of	FOC	,
	· Smoke A	lam	
	- Smuch (a)	Eminees	
		9	
1			
l lon	mon		281 7 120 IH
Accredited Certifi	er-BPB OIRH		Date



# Electrical Pty Ltd

ABN: 70 121 479 883 Licence No: 220811C

PO BOX 1182, NEWPORT 2106

Matt Griffiths: 0414 280 480

Luke Griffiths: 0405 310 090

#### To Whom It May Concern:

JOB: 16A REDNAL ST MONA VALE

As licensed electrical company we installed 2 x 240 volt smoke detectors with battery backup , to meet standards from AS3786-1993 and AS3000-2007 + in accordance with the requirements of part 3.7.2 of the building code of Australia(vol 2) at the above address.

LUKE GRIFFITHS

DIRECTOR



## Jack Hodgson Consultants Pty Limited

CONSULTING CIVIL, GEOTECHNICAL AND STRUCTURAL ENGINEERS

ABN: 94 053 405 011

MN 28445B. 4<sup>th</sup> September, 2014. Page 1.

The General Manager Pittwater Council P O Box 882 MONA VALE NSW 1660

Dear Sir,

#### 16A REDNAL STREET, MONA VALE.

On the 31<sup>st</sup> July, 2014 we inspected the framing for the proposed alterations and additions at the rear of the subject address.

At the time of our inspection the framing was in accordance with our drawing number 28445-S1 & our letter MN28445A, AS 4100 & 1720 and our on site instructions.

JACK HODGSON CONSULTANTS PTY. LIMITED.

DIRECTOR: N. J. HODGSON 67 Darley Street, Mona Vale NSW 2103 PO Box 389 Mona Vale NSW 1660 Telephone: 9979 6733 Facsimile: 9979 6926 www.jackhodgson.com.au