


CHECKLIST FOR COUNCIL'S ASSESSMENT OF SITE CONDITIONS AND NEED FOR GEOTECHNICAL REPORT IN GEOTECHNICAL CLASS B AND D



GEOTECHNICAL NOTES:

- Zone: G3
- Description: Beach foredune and alluvial flats
- Slope: < 5 degrees
- Follow good engineering practice

Completed by
Tania Landsdorff, Lux Landscapes
25/10/2023 for residential property at
53 Eurobin Avenue, Manly