STEPHEN PINN

Accredited Certifier BPB 0326



Determination of a Final Occupation Certificate Application

Made under Sections 109C(1)(c) and 109H of the Environmental Planning and Assessment Act 1979

Final Occupation Certificate No: 2008/2522

Land to which this certificate applies:

Address: 1 Bilberry Avenue, Bilgola Plateau

Lot No:13

DP No:24536

I approve the issuing of this Final Occupation Certificate and certify that:

- I have been appointed as the Principal Certifying Authority under Section 109E of the Environmental Planning & Assessment Act 1979.
- Current Development Consent No. N0208/07 is in force for this development.
- Construction Certificate No. 2008/2522 has been issued with respect to the plans and specifications for alterations and additions to an existing dwelling.
- The building is completed in accordance with its classification under the Building Code of Australia.
- Refer to various certificates, documentation and inspection reports attached.

Determination date:

2 5 APR 2014

Stephen Pinn

Accredited Certifier - Accreditation No. BPB0326

P-370/92 in

Phone: 0404 332 978



BUILDING INSPECTION REPORT

Land to which this Building Inspection R	•	/			
Council Area :	Date of Insp	pection			
Council Area : Silberry	Ae, Bilgola	Plateau !			
DA No	CC No 2018/25	22 CDC No			
Requested by:					
Critical Stage Inspections					
Site Assessment - Pre CC/ CDC Issue	Footings and Excavation	Waterproofing			
PCA Signage	Steel Placement	Stormwater			
Sediment Controls	Floor Framing / Slab	Pool Fence			
Tree Protection Measures	Wall Framing	Final Inspection			
Building Commencement	Roof Framing	Photographic record			
Other (specify)					
An inspection of Ste Assessment has been carried out and has been found to be in compliance with the plans and specifications as approved in that Construction Certificate/Complying Development Certificate. Complete the work detailed hereunder.					
Complete the work detailed hereunder and contact the Principal Certifying Authority to arrange a re-inspection. NB A re-inspection fee of \$ will be charged, which is payable PRIOR TO THE RE-INSPECTION BEING CARRIED OUT.					
- satisfacts					
	· · · · · · · · · · · · · · · · · · ·				
Signed: Accredited Building Surveyor	ccreditation No. <i>IBB</i>	Date: 14/1/2008			



BUILDING INSPECTION REPORT

	Date of In	spection
Address / Bikhen	ny Avenue Belgi	da Phriteau
DANO NO 208/07	CC No 2068/2522	CDC No
Requested by: Crain Pa	ppole tom Ph No.	0410 425 598
Requested by:	-/ Ph No.	······································
ritical Stage Inspections		
PCA Signage	Steel Placement	stormwater
Sediment Controls	Floor Framing / Slab	Pool Fence
Tree Protection Measures	Wall Framing	Final Inspection
Building Commencement	Roof Framing	Other (specify)
Footings and Excavation	Waterproofing	Photographic record
Construction Certificate/Comply	ing Development Certificate.	
Complete the work detailed here Complete the work detailed here re-inspection. NB A re-inspection THE RE-INSPECTION BEING	reunder. reunder and contact the Principal Confee of \$will be cha	rged, which is payable PRIOR
Complete the work detailed here Complete the work detailed here re-inspection. NB A re-inspection THE RE-INSPECTION BEING	reunder. reunder and contact the Principal Confee of \$will be cha	ertifying Authority to arrange rged, which is payable PRIOR
Complete the work detailed here Complete the work detailed here re-inspection. NB A re-inspection THE RE-INSPECTION BEING	reunder and contact the Principal Confee of \$ will be cha	rged, which is payable PRIOR



BUILDING INSPECTION REPORT

	Date of Ins	spection
	an Chalarena l'Island	e MaNeur
	CC No. 2008/2522	
Requested by: Yank	Ph No.	BU19 229813
itical Stage Inspections		
PCA Signage	Steel Placement	Stormwater
Sediment Controls	Floor Framing / Slab	Pool Fence
Tree Protection Measures	Wall Framing	Final Inspection
Building Commencement	Roof Framing	Other (specify)
Footings and Excavation	Waterproofing	Photographic record
An inspection of	enolfing to ensure	has been carried
Construction Certificate/Compl	ying bevelopment certificate.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspecti	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	
Complete the work detailed her Complete the work detailed he re-inspection. NB A re-inspection THE RE-INSPECTION BEING	eunder. reunder and contact the Principal Coin fee of \$will be chase CARRIED OUT.	

	FINAL INSPECTION REPORT				
	Land to which this Final Inspection Report result sheet applies:				
	Council Area Pttrate Date of Inspection 17/5/2013				
	Council Area PHrate Date of Inspection 17/5/2013 Address BILBERRY AVE BILGUA PLATEAU				
•	DA No CC No. 2008/2522 CDC No				
	DA No. CC No. 2008/2522 CDC No. Requested by: Ph No. 9918 - 3568				
	Certificates Required				
V	Wet Area Certification				
	Submission of a compliance certificate from an appropriately qualified person verifying the waterproofing of all wet areas were carried out in accordance with the requirements of AS 3740 - Waterproofing of Wet Areas in Residential				
	Buildings. Structural Engineers Certification (see attached inspection separt)				
	Smoke Alarm Certification				
	Submission of a certificate from a licensed Electrician confirming all required smoke alarms have been installed in accordance with the requirements of Part 3.7.2 of the Building Code of Australia (Vol. 2).				
	Glazing Certification windows / closes				
	Submission of a glazing certificate confirming all glazing has been supplied and installed to satisfy the requirements of AS 1288 - 2006.				
	Termite Control Certification Statement from Staller Coney) 811 brilission of a certificate from a licensed past controller confirming termite protections have been provided in				
	accordance with AS 36601.				
	BASIX Compliance Statement Continuing all requirements have been satisfied.				
	Stormwater Certification Submission of a certificate from an appropriately qualified NPER Civil Engineer verifying the adequacy of the stormwater				
AND THE PROPERTY OF THE PARTY O	drainage system as installed				
PARTICIONAL PROPERTY AND IN COLUMN	Survey Certification				
Constant Constant	Submission of a certificate from Registered Surveyor confirming the set-out of building & finished ridge height.				
and in succession	Resuscitation Chart A Resuscitation Chart is to be affixed and displayed within the swimming pool area.				
A CONTRACTOR OF THE PARTY OF TH					
*					
SHAMBARK PRO	·				
TAT THE PROPERTY OF THE PARTY O	A				
THE OF STREET, CASE OF	Signed: Accreditation No. BPB0326 Date:				
Philips or had substituted in	Stephen Pinn Accredited Building Certifier				
TECHNOLOGY WAS A STORY COST	PO Box 136 More Vale NSW 1560 ph: 0404332976 Email: stephenpinc00@gmail.com ABN 88 691 592 147				

SUPER-JET CONSTRUCTIONS PTY.LTD.

ABN: 90 084 024 251 ACN: 084 024 251 Lig.No. 114035C

A CURRENT MEMBER OF THE M.B.A. P.O. BOX 691 DRUMMOYNE NSW 1470 JOHN A CASSIDY DIRECTOR

PHONE/FAX: 02 9819 6899 MOBILE: 0414 647 734 john_superjet@yahoo.com.au

www.superjetconstructions.com.au

DATE: 1/06/04

CERTIFICATE WARRANTY

TO WHOM IT MAY CONCERN

Super-Jet Waterproofing Services are approved and preferred by following companies:

- WESTOX PTY LTD.
- * FIBERGLASS (A / ASIA) SALES PTY LTD.
- * SWEPDRI INTERNATIONAL PTY LTD.
- * LASER SONICS PTY LTD.
- DUROTECH INDUSTRIES PTY LTD.
- * TECH-DRY PTY LTD.
- SYDNEY TRADE CENTRE PTY LTD.

The waterproofing products used have either H.I.A/Absac or government approval certificates.

The waterproofing has been applied in accordance to the manufactures standards and requirements.

All waterproofing application complies with Australian Standards(#3740) (Conditions Apply)

Superjet Constructions Pty Ltd. follows the Australian Standards Waterproofing Codes.


Total warranty period of 7 years.

SITE ADDRESS: 1 BILBERRY STREET, BILGOLA.

Signed and approved by the Director of SuperJet Constructions Pty Ltd:

moko

THANK YOU FOR SUPPORTING A 100 % AUSTRALIAN OWNED COMPANY.
SUPER-JET CONSTRUCTIONS PTY LTD.
REGARDS, JOHN & CASSIDY.



Barrenjoey Constructions -

37 The Outlook, Bilgola Plateau, NSW 2107 ABN 40 964 774 297

Contractor Licence No. 137445C

C & C Poppleton

Ph: 0410 475 598 Ph/Fax: 9918 7258

Email: cpoppleton@bigpond.com

1st June 2010

DA NO: 208/07

CC NO: 2008/2522

Compliance Certificate for Termite Control

Property at 1 Bilberry Avenue, Bilgola.

This is to certify that the physical termite barrier to the extension of the property above was installed in accordance with the relevant sections of the BCA, to manufacturers recommendations and to conditions of consent. This certificate covers the new addition only and does not imply that the existing termite barriers are adequate.

Termite inspections must be carried out every twelve months by an appropriately qualified pest inspector or all warranties are void.

I am appropriately qualified and experienced to provide this certificate.

C. Poppleton. (Master Builder)



Our Reference: SY070659

31 May 2010

Barrenjoey Constructions 37 The Outlook BILGOLA PLATEAU NSW 2107

Attn:

Mr Craig Poppleton

Re:

Final Structural Certification 1 Bilberry Avenue, Bilgola Plateau

This is to certify that structural inspections were carried out during construction of this project by a practicing Structural Engineer in accordance with accepted engineering practice and principles.

At the time of each inspection, the work inspected generally conformed, in our opinion with the structural engineering drawings. Where minor corrections were required, written instructions were issued to the Builder for their correction.

Elements covered by this certificate include:

- Footings, foundations and retaining walls
- Concrete slabs on ground
- Timber wall, floor and roof framing
- Steel wall and roof framing

This certificate does not relieve the Builder or any other party of their responsibilities for the project.

Yours sincerely,

ACOR Consultants Pty Ltd

Chris Rowse BE, MIEAust, CPEng

Director

ACOR CONSULTANTS PTY LTD

ENGINEERS

MANAGERS

INFRASTRUCTURE PLANNERS

SYDNEY - BRISBAND - NEWGASTLE GOSFORD - ADELAIDE

ACN 073 306 246

ABN 26 522 464 721

Level 1, 24 Falson Street

PO Box 822

Crows Near MSW 2065

02 9433 5098

02 9438 5398

Page Loff www.acci.com.au

Positively Electric 106 Plateau Road Bilgola NSW 2107

Phone: 0423 413998 Licence #: 189703C ABN: 38450286642

Dated: 28 June, 2013

To Whom It May Concern,

We hereby certify 1 x 240 / 9V hardwired battery back up smoke detector which complies with AS3786 has been installed at ;

1 Bilberry Avenue Bilgola NSW 2107

The electrical installation complies with the Wiring Rules AS3000.

Signed

Enno Wiese Electrical Contractor Positively Electric